

Document Separator Sheet



Document Title:

NAVSEADET RASO TECHNICAL ASSISTANCE VISIT

Document ID/File Name:

2081



Document Date:

5/4/1987

In NRIS:

NO

Installation:

Author Affiliation:

P.J. DUPREE

Contract Number/CTO:

Command:

MARIANAS

Notes:

Original Box #:

64

MSI Scan Box #:

57

61119 A
NSD, Guam, MI

ONE
DOK



8128/3252.26A
Ser 02C/0411
04 MAY 1987

From: Officer in Charge
To: Commanding Officer, U.S. Naval Supply Depot, Guam,
FPO San Francisco 96630-1500

Subj: NAVSEADET RASO TECHNICAL ASSISTANCE VISIT

Ref: (a) NSD Guam ltr 8128 Ser 05/490 of 6 Mar 87
(b) NAVSEADET RASO Report No. 3252.26A1

1. Reference (a), delineating actions completed to correct items noted in reference (b) has been reviewed and is considered adequate. The following changes should be made to NSD GUAM INST 5100.4 and 5100.5 for clarity:

a. NSD GUAM INST 5100.4:

(1) Paragraph 5.a(2). The Radiation Safety Officer (RSO) should be appointed in writing.

(2) Paragraph 5.b(2). The RSO should maintain training records for personnel who work with radioactive materials.

(3) Sentence 6.d should read "No Unauthorized Entry, No Loitering".

(4) Section 10-C.1. Retain evacuated personnel close to the warehouse area to prevent spread of contamination and to enable personnel to be whole body frisked for contamination.

(5) Section 10.d. Delete words "copy to SPAWAR Code 815" and add: notify NAVSEASYS COM (CEL-R) (to be notified for loss of RADIAC check source materials only) and NAVSEADET RASO.

b. NSD GUAM INST 5100.5, enclosure (1), paragraph III.2.d. Change to read: A reading of 50 cpm or greater on the AN/PDR-56 meter indicates presence of alpha contamination and notifications will be made per Section III.3.

2. For assistance contact CDR J. W. Malinoski, or Mr. H. E. Roush, AUTOVON 953-4692, or Commercial (804) 837-4692.

P. J. DURFEE