

# Document Separator Sheet



**Document Title:**

RADIOLOGICAL AFFAIRS TECHNICAL ASSISTANCE VISIT

**Document ID/File Name:**

3589



**Document Date:**

2/6/1981

**In NRIS:**

NO

**Installation:**

AGANA\_NAS

**Author Affiliation:**

NAVAL ENERGY AND ENVIRONMENTAL SUPPORT ACTIVITY

**Contract Number/CTO:**

**Command:**

MARIANAS


**Notes:**

**Original Box #:**

80

**MSI Scan Box #:**

69





OFFICER IN CHARGE  
NAVAL ENERGY AND ENVIRONMENTAL SUPPORT ACTIVITY  
PORT HUENEME, CALIFORNIA 93043

113 ~~BD~~  
(TRAY)

IN REPLY REFER TO:  
412:TRB:lm  
3252.25A  
Ser: 141


6 FEB 1981

From: Officer in Charge  
To: Commanding Officer, U.S. Naval Air Station, FPO San Francisco 96637

Subj: Radiological Affairs Technical Assistance Visit

Ref: (a) NEESA ltr Ser 1144 of 12 Sep 80  
(b) Radiological Affairs Support Office Report No. 117B of 12 Sep 80

1. A reply, as requested in reference (a), delineating actions taken and/or planned to correct items noted in reference (b), has not been received.
2. It is requested that an expeditious reply to reference (b) be forwarded to this Activity. Questions concerning this correspondence should be directed to Mr. John J. Orr, Naval Energy and Environmental Support Activity, Radiological Affairs Support Office, AUTOVON 360-4161.

  
R. H. SMITH  
By direction

Copy to:  
NAVFACENGCOM (111N)  
NAVAIRSYSCOM (5324K)