



DEPARTMENT OF THE NAVY
NAVAL FACILITIES ENGINEERING COMMAND, PACIFIC
258 MAKALAPA DR., STE. 100
PEARL HARBOR, HAWAII 96860-3134

5090.B14
Ser EV4577

23 JUL 2008

To: Distribution

SUBJECT: 6-MONTH POST REMEDIATION INSPECTION REPORT, FORMER LOWER SASA FUEL BURNING POND, COMNAVMARIANAS, PITI, GUAM

Enclosed for your information and retention is the 6-Month Post Remediation Inspection Report for the Former Lower Sasa Fuel Burning Pond, COMNAVMARIANAS, Piti, Guam.

The 6-month inspection report documents the findings of the first post-remediation inspection performed at the site in March 2008. Results of the inspection indicate that oxygen reducing conditions are present in the open water habitat as planned. Additionally, all areas evaluated displayed health communities of the species planted.

Should you have any questions, please contact Ms. Joanna Victorino of our Environmental Restoration Product Line at (808) 472-1433.

Sincerely,

A handwritten signature in black ink, appearing to read "Karen C. Sumida".

KAREN C. SUMIDA
Business Line Manager
Environmental

Enclosure: Final 6-Month Post Remediation
Inspection Report, Former Lower
Sasa Fuel Burning Pond,
COMNAVMARIANAS, Piti, Guam
of Jul 08

5090.B14
Ser EV4/577

23 JUL 2008

Distribution:

Mr. Michael Wolfram
Pacific Islands Office (CED-6)
U. S. Environmental Protection Agency
Region IX
75 Hawthorne Street
San Francisco, CA 94105

Mr. Roland T. Gutierrez
Guam Environmental Protection Agency
Guam Main Facility
P. O. Box 22439
Barrigada, GU 96921

Ms. Laurie Sullivan
NOAA Regional Resources Coordinator
c/o NOAA Restoration Center
777 Sonoma Avenue Ste 219A
Santa Rosa, CA 95404

Mr. Jeff Newman
U. S. Department of Interior
Fish and Wildlife Service
300 Ala Moana Blvd., Suite 3-122
Honolulu, HI 96850

Mr. Francis Dayton
U. S. Army Corps of Engineers
Guam Regulatory Branch
PSC 455, Box 188
FPO AP 96540-1088

Mr. Paul Bassler, Chief
Aquatic and Wildlife Resources
Department of Agriculture
192 Dairy Road
Mangilao, GU 96923